

U.S. DEPARTMENT OF LABOR

WORKPLACE STANDARDS ADMINISTRATION NO BUREAU OF LABOR STANDARDS

Deleter

FORM NO OSHA-20 (MODIFIED MAY 1971

DPM - 1777-1 MDC CONTROL NO._____

MATERIAL SAFETY DATA SHEET

SECTION I	: MAT	ERIAL AND MA	ANUFACTURER IDENTIFICATION							
MANUFACTURER'S NAME EMERGENCY TELEPHONE NO										
Churchill Chemical Corp. (213) 269-9461										
ADDRESS (NUMBER, STREET, CITY, STATE AND ZIP CO	DDE)		00013							
3137 E. 26th Street, LosAng	зете	es, Ca.								
CHEMICAL NAME AND SYNONYMS			TRADE NAME AND SYNONYMS							
Polysulfide CHEMICAL FAMILY		3C-1300 Frozen								
Polysulfide										
SECTION II: HAZARDOUS INGREDIENTS*										
PAINTS, PRESERVATIVES/SOLVENTS	%	TLV (UNITS)	ALLOYS AND METALLIC COA	ATINGS %	TLV (UNITS)					
PIGMENTS Carbonates-Lithopone	30		BASE METAL							
CATALYST Lead Peroxide	10		ALLOYS							
J	60		METALLIC COATINGS	The Chapter of the Control of the Co						
DLVENTS			FILLER METAL PLUS							
	1.5		COATING OR CORE FLUX							
Adhesion Promoter ~	2		OTHERS							
OTHERS										
	<u> </u>				TLV					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES* %										
	·	SECTION UIL F	HYSICAL DATA							
BOILING POINT (⁰ F)			SPECIFIC GRAVITY (H ₂ O = 1)							
BOILING FOINT (F)		NA								
VAPOR PRESSURE (mm Hg.) NA		NA	PERCENT VOLATILE BY VOLUME (%)							
VAPOR DENSITY (AIR = 1)			EVAPORATION RATE (= 1)							
SOLUBILITY IN WATER		NA								
APPEARANCE AND ODOR Tan to Brown	-44346869588 - 5									
	'I NOI	V: FIRE AND E	XPLOSION HAZARD DATA							
FLASH POINT (METHOD USED) Open cup 180°F			FLAMMABLE LIMITS	Lel	Uel					
CO2, water, dry chemicals										
SPECIAL FIRE FIGHTING PROCEDURES None										
LINUISUAL FIDE AND EVELOCION HAZADOS										

*PLEASE DO NOT USE GENERALIZATIONS, SUCH AS PETROLEUM HYDROCARBONS, ALCOHOL, KETONES.

USE SPECIFIC CHEMICAL NAMES, SUCH AS METHANOL, BENZENE, PERCHLOROETHYLENE.

MDC 363(20 SEP 71)

None

		Solidard	SEC.	TION	V: HEALTH HAZARD DA	NTA		
THRESHOLD LIMIT VALU	E 5-8 g/k	cilo	Section of the second	HON	V. IILALIII IIAZAND DA	I I A		
EFFECTS OF OVEREXPO	SURE							
	kin or eye i	rri	tatio	าก				
	KIII OI Cyc I				0.000 (0.			
EMERGENCY AND FIRST	AID PROCEDURES		100					
Wash affect	ed area thor	oug	h t y v	vit	h soap and wa	ter, in ca	se of eye co	ntact
use clear w	ater. Call P	hys	ican		,			
					N VI: REACTIVITY DATA			
	UNSTABLE	UNSTABLE COND			TO AVOID			
STABILITY	STABLE	X						
INCOMPATIBILITY (MATE	RIALS TO AVOID) None							
HAZARDOUS DECOMPOSIT								
	Sulfides							
114 74 BB0110	MAY OCC	UR	i		CONDITIONS TO AVOID			
HAZARDOUS POLYMERIZATION					High tempe	ratures	And the state of t	
TOLINENIZATION	WILL NOT	WILL NOT OCCUR			Over 300	°F	Walter State of the State of th	· · · · · · · · · · · · · · · · · · ·
					: SPILL OR LEAK PROCE	DURES		
STEPS TO BE TAKEN IN O	CASE MATERIAL IS RE							
			<u>kegu.</u>	<u>lar</u>	Clean-up			
*								
			4					
WASTE DISPOSAL METHO		D	4					
		Keg	ular	wa	ste disposal			
		·····						
		SECT	TION VII	I: SP	ECIAL PROTECTION INF	ORMATION		
RESPIRATORY PROTECTI	No special	n 220	+00+1	an				
Control of the Contro	LOCAL EXHAUST			.011		SPECIAL		
VENTILATION MECH			Yes	_		I	None	
	MECHANICAL (GENEI	CHANICAL (GENERAL)						
PROTECTIVE GLOVES	Recommended EYE PROTEC					<u>L</u> TION Recommende		
OTHER PROTECTIVE EQU		iiue	u 	**********		Recommende	3	
	No	ne						
			SECT	ION	IX: SPECIAL PRECAUTIO	INS	1	
PRECAUTIONS TO BE TAI Wasl				an	dling, store	below 85°F	•	
					0°F for froze			
OTHER PRECAUTIONS	one							
IVC	J.							
M.B. Smith	M. S. Sm	ith	, ,		4/75			
PREPARED BY	And I have been seen to the second se		and the same of th		DATE	ACCESSORY.		

DATE